CarOn oy · Lampputie 12 C 67, 00750 Helsinki
+358 45 312 4202 · huolto@caron.fi

Demo · example data

Maintenance report

Vehicle
EX-022 · Toyota Corolla Touring Sports 2023

Fleet
Example Company

Based at
Helsinki site

Mileage at last visit
27,310 km

Period
13 May 2026 to 22 Sept 2026

Report made
19 Nov 2026

Summary of visits

Date	Mileage	Work	Parts used	Off the road	Cost excl. VAT
22 Sept 2026	27,310 km	Rear lamp bulb	Brake lamp bulb	40 min	21.80 €
13 May 2026	15,160 km	Service, 15,000 km	Oil filter · Cabin filter	3 h	178.40 €
Total, 2 visits				**3 h 40 min**	**200.20 €**

Itemisation for your records. Amounts exclude VAT. One visit is in progress: Service, 30,000 km. It joins this report when it is finished.

22 Sept 2026 · Rear lamp bulb

Came in 22 Sept 2026 at 13:00 · ready 22 Sept 2026 at 13:40 · off the road 40 min · 27,310 km

What we found

Left rear brake lamp out.

What we did

Bulb replaced, all lamps checked.
Work by Mikko (example name)

Cost

Brake lamp bulb	4.30 €
Labour, fixed for this job	17.50 €
Total excl. VAT	**21.80 €**

13 May 2026 · Service, 15,000 km

Came in 13 May 2026 at 08:00 · ready 13 May 2026 at 11:00 · off the road 3 h · 15,160 km

What we found

No fault found. Front pads 9 mm, rear 8 mm.

What we did

Oil and oil filter changed, cabin filter changed.
Work by Antti (example name)

Cost

Engine oil to the maker's specification	56.40 €
Oil filter	14.30 €
Cabin filter	23.70 €
Labour, fixed for this job	84.00 €
Total excl. VAT	**178.40 €**

CarOn oy · Example report made for this demonstration on 19 Nov 2026. No real vehicle, customer or price is shown.